



DEPARTMENT OF
WATER RESOURCES

DELTA AREA *Fact Sheet* **Site 32.5**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 32.5

Latitude/Longitude:

38.306128/-121.574547

Nearest Impact Area:

Clarksburg

County: Sacramento

Bank: Right

Type of Damage

Bank erosion

Length of Repair

2,300 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources

**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

